



MARIE REED REC LEAD WATER TEST RESULTS

May 16th, 2016



	Building Location	Sample Collected Date	Water Source ID	Device Type	Floor	Device Location	1st Draw - Sample ID	Final Result - 1st Draw (ug/L)	2nd Draw - Sample ID	Final Result - 2nd Draw (ug/L)	Remediation	Retest Date	Retest 1st Draw	Retest 2nd Draw
1	MARIE REED RECREATION CENTER	5/27/2016	WS- 012024	Cooler	1	In gym (on basketball court)	WT-042916-12041- A	< 1	WT-042916-12041- B	< 1				
2	MARIE REED RECREATION CENTER	5/27/2016	WS- 012025	Cooler	1	In hallway adjacent to men's restroom	WT-042916-12042- A	< 1	WT-042916-12042- B	1.3				
3	MARIE REED RECREATION CENTER	5/27/2016	WS- 012026	Cooler	Ground Floor	In hallway adjacent to women's restroom	WT-042916-12043- A	< 1	WT-042916-12043- B	< 1				

Footnotes:

A - First draw sample is collected after the plumbing system has not been used for at least 6 hours.

B - Second draw sample is collected after a 60 second flush at that device after the first draw.